New South Wales Government

ABC FOI 2016-038 Document 1

147

Department of Industrial Relations

N. Caruana Head of Building Services A.B.C. GPO Box 9994 SYDNEY 2001 00 Joseph Streel Lidcombe, N.S.W. 2141 Address reply to P.O. Box 163, Lidcombe, N.S.W 2141

3963

Our reference Your reference

> 1/5/28:CT:JMcB Phone: 646 0222

, ( { • • • •

Correct F+ 50 QA/7

15 June 1984

ANALYSIS

| Sample No.  | Submitted by                                       |                                       | Date Received                                    |         |
|---|--|---------------------------------------|--|---------|
| ε.  |  |                                       | 1  |         |
| D412  | N. Caruana   |                                       | 1/6/84   | \$      |
| Origin of Sample<br>Sample from ceiling i   | nsulation - St                                     | udio 22, Gore                         | e Hill   |         |
|   | ч <u>с</u>   |                                       | 190 - 180  |         |
| Description of Sample   | ,  | Assay Result                          | ts.  |         |
| Soft brown fibrous ma   | aterial .  | Amosite a                             | asbestos   | ÷       |
|   | 8<br>3   |                                       | 92<br>24   | 8.<br>1 |
| ix<br>Na  | 00   | E                                     | *  | ŝ.      |
| Remarks<br>The sample was analys<br>amosite asbestos as a<br>Any work carried out<br>Regulation 84A-J "Co<br>Cement" 1983, as amo | a major compone<br>on the above<br>onstruction Wor | ent.<br>materials to<br>k Involving A | be in accordance w<br>Asbestos or Asbesto        | with .  |
| * <u></u> {   |  |                                       | ž *  |         |
| C.L.  |  |                                       | AY<br>AY<br>Fficer (Scientific<br>Hygiene Branch | ) *     |

R.C. JONES Officer in Charge Industrial Hygiene Branch For Director

EVA FRANCIS Scientific Officer

| N. Caruana<br>Head of Buildin<br>Australian Broa<br>145-153 Elizabe     | Division<br>g Services<br>dcasting Corp.             | dustrial Relations<br>of Occupational Healt<br>Joseph Street<br>Lidcombe, N.S.W. 2141<br>Address reply to<br>P.O. Box 163, Lidcombe |                    |
|---|--|---|--------------------|
|   | 0 00   | Your relerence 1/5/2  | 8963<br>28:ct:JMcB |
|   | · · · · ·  | PI  | honø: 646 0222     |
|   | 201  |   | *                  |
|   | ANALYS   | <u>15.8.84</u>  |                    |
| Sample No.  | Submitted by   | Date Received   | 1                  |
| D629 D630   | N. Caruana   | 31.7.84   |                    |
|   | с  |   | 14                 |
| Origin of Sample<br>PROPERTY STORE,<br>D629 Painted f<br>D630 Unpainted | GORE HILL<br>ibro                                    |   | ×                  |
| Description of S  | ample As   | ssay Results  |                    |
|   | painted side   | Chrysotile asbestos & cel<br>in a bonded cement matri<br>mosite asbestos & cellul<br>bonded cement matrix.                          | x.<br>.ose in a    |
|   |  | 2   |                    |
| -   |  | 58  | 21                 |
| Any work carrie<br>Regulation 84A-                                      | d out on the above mater<br>J "Construction Work Inv | microscopy and the resu<br>ial is to be in accordan<br>olving Asbestos or Asbes<br>SW Construction Safety A                         | ce with<br>tos     |
|   | <u>*</u>   | · · ·   |                    |
|   | 1  | ×   |                    |
| 16. y   | R  | MAYO-RAMSAY   | ;ific)             |

۰,

For Direc

# ABC FOI 2016-038 Document 2

Hill Mr.

EVA FRANCIS

ABC FOI 2016-038 Document 3

# A.B.C. INTER - OFFICE MEMORANDUM

| To:<br>Subject: INTERIM REPORT ON ASBESTOS - GORE HILL STUDIOS  | From (Desig'n):  | <u>    FedFP&amp;SO</u><br>GDG:JS | (Dep't/State):      | HO                  | Phone Ext'n:   | <u> </u>   |
|---|------------------|-----------------------------------|---------------------|---------------------|----------------|------------|
| els<br>Mr. K. Connolly<br>On phoning the Commonwealth Institute of Health on 13.8.84, the<br>following information has been verbally given:-<br><u>Static Samples</u><br>1) Ceiling of studio 21<br>2) Airconditioning intake studio 21<br>3) Behind insulating tiles studio 23<br>4) Control Room 23<br>5) Iron Roof studio 22<br>Air Sampling Result<br>All samples analysed gave a negative result, i.e., there were no<br>measurable amounts of asbestos.<br>This information was related by Mr. G. Dennis and he advised that<br>complete written report would be forthcoming as early as possible.<br><i>M.D. GuoryBon</i><br><i>G.D. GEORGESON</i>   | Our Ref/File No: |                                   | Your Ref/File No:   |                     | Date:          | 11.0.04    |
| els<br>Mr. K. Connolly<br>On phoning the Commonwealth Institute of Health on 13.8.84, the<br>following information has been verbally given:-<br><u>Static Samples</u><br>1) Ceiling of studio 21<br>Asbestos (Amosite)<br>2) Airconditioning intake studio 23<br>3) Behind insulating tiles studio 23<br>4) Control Room 23<br>5) Iron Roof studio 22<br><u>Air Sampling Result</u><br>All samples analysed gave a negative result, i.e., there were no<br>measurable amounts of asbestos.<br>This information was related by Mr. G. Dennis and he advised that<br>complete written report would be forthcoming as early as possible.<br><u>M.D. GLORGESON</u>  | To:              |                                   | 2                   |                     |                |            |
| Mr. K. Connolly       On phoning the Commonwealth Institute of Health on 13.8.84, the following information has been verbally given:-         Static_Samples       Results         1)       Ceiling of studio 21       Asbestos (Amosite)         2)       Airconditioning intake studio 21       Non-Asbestos         3)       Behind insulating tiles studio 23       Non-Asbestos         4)       Control Room 23       Non-Asbestos (Amosite)         5)       Iron Roof studio 22       Asbestos (Amosite)         Air Sampling Result       All samples analysed gave a negative result, i.e., there were no measurable amounts of asbestos.         This information was related by Mr. G. Dennis and he advised that complete written report would be forthcoming as early as possible.         M.D. McongWa         G.D. GEORGESON  |                  | Subject:                          | NTERIM REPORT ON A  | SBESTOS - GORE HI   | LL STUDIOS     |            |
| on phoning the commonwealth Institute of Health on 13.8.84, the<br>following information has been verbally given:-<br><u>Static Samples</u><br>1) Ceiling of studio 21<br>2) Airconditioning intake studio 23<br>3) Behind insulating tiles studio 23<br>4) Control Room 23<br>5) Iron Roof studio 22<br>Air Sampling Result<br>All samples analysed gave a negative result, i.e., there were no<br>measurable amounts of asbestos.<br>This information was related by Mr. G. Dennis and he advised that<br>complete written report would be forthcoming as early as possible.<br><i>M.D. McoryBar</i><br><i>G.D. GEORGESON</i>   | lels             |                                   | 2                   | 5945                |                |            |
| following information has been verbally given:- Static_Samples Results   1) Ceiling of studio 21 Asbestos (Amosite)   2) Airconditioning intake studio 21 Non-Asbestos   3) Behind insulating tiles studio 23 Non-Asbestos   4) Control Room 23 Non-Asbestos   5) Iron Roof studjo 22 Asbestos (Amosite)   Air Sampling Result All samples analysed gave a negative result, i.e., there were no measurable amounts of asbestos. This information was related by Mr. G. Dennis and he advised that complete written report would be forthcoming as early as possible. <i>Machardreet Witten Result Machardreet Witten Result Machardreet</i> | Mr. K. Conn      | on phonir                         | ng the Commonwealth | Institute of Hea    | 1th on 13.8    | .84. the   |
| <ul> <li>1) Ceiling of studio 21 Asbestos (Amosite)</li> <li>2) Airconditioning intake studio 21 Non-Asbestos</li> <li>3) Behind insulating tiles studio 23 Non-Asbestos</li> <li>4) Control Room 23</li> <li>5) Iron Roof studio 22 Asbestos (Amosite)</li> </ul> Air Sampling Result All samples analysed gave a negative result, i.e., there were no measurable amounts of asbestos. This information was related by Mr. G. Dennis and he advised that complete written report would be forthcoming as early as possible. <i>B.D. GEORGESON</i>  |                  |                                   |                     |                     |                | ,          |
| <ul> <li>1) Ceiling of studio 21 Asbestos (Amosite)</li> <li>2) Airconditioning intake studio 21 Non-Asbestos</li> <li>3) Behind insulating tiles studio 23 Non-Asbestos</li> <li>4) Control Room 23</li> <li>5) Iron Roof studio 22 Asbestos (Amosite)</li> </ul> Air Sampling Result All samples analysed gave a negative result, i.e., there were no measurable amounts of asbestos. This information was related by Mr. G. Dennis and he advised that complete written report would be forthcoming as early as possible. <i>B.D. GEORGESON</i>  |                  |                                   |                     |                     |                | 33         |
| <ul> <li>1) Ceiling of studio 21 Asbestos (Amosite)</li> <li>2) Airconditioning intake studio 21 Non-Asbestos</li> <li>3) Behind insulating tiles studio 23 Non-Asbestos</li> <li>4) Control Room 23</li> <li>5) Iron Roof studio 22 Asbestos (Amosite)</li> </ul> Air Sampling Result All samples analysed gave a negative result, i.e., there were no measurable amounts of asbestos. This information was related by Mr. G. Dennis and he advised that complete written report would be forthcoming as early as possible. <i>B.D. GEORGESON</i>  |                  | Static Sa                         | amples              |                     | Results        |            |
| <ul> <li>2) Airconditioning intake studio 21 Non-Asbestos</li> <li>3) Behind insulating tiles studio 23 Non-Asbestos</li> <li>4) Control Room 23 Non-Asbestos</li> <li>5) Iron Roof studio 22 Asbestos (Amosite)</li> </ul> Air Sampling Result All samples analysed gave a negative result, i.e., there were no measurable amounts of asbestos. This information was related by Mr. G. Dennis and he advised that complete written report would be forthcoming as early as possible. <i>M. D. M. M.</i>   |                  |                                   |                     |                     |                |            |
| 3) Behind insulating tiles studio 23 Non-Asbestos<br>4) Control Room 23 Non-Asbestos<br>5) Iron Roof studio 22 Asbestos (Amosite)<br><u>Air Sampling Result</u><br>All samples analysed gave a negative result, i.e., there were no<br>measurable amounts of asbestos.<br>This information was related by Mr. G. Dennis and he advised that<br>complete written report would be forthcoming as early as possible.<br><u>J D. GEORGESON</u><br><u>G.D. GEORGESON</u>   |                  |                                   |                     |                     |                |            |
| <ul> <li>4) Control Room 23</li> <li>5) Iron Roof studio 22</li> <li>Asbestos (Amosite)</li> <li>Air Sampling Result</li> <li>All samples analysed gave a negative result, i.e., there were no measurable amounts of asbestos.</li> <li>This information was related by Mr. G. Dennis and he advised that complete written report would be forthcoming as early at possible.</li> <li><i>M.D. M.Corygea</i></li> <li><i>G.D. GEORGESON</i></li> </ul>   | 9 <b></b> (      |                                   |                     |                     |                |            |
| 5) Iron Roof studio 22<br><u>Air Sampling Result</u><br>All samples analysed gave a negative result, i.e., there were no<br>measurable amounts of asbestos.<br>This information was related by Mr. G. Dennis and he advised that<br>complete written report would be forthcoming as early as possible.<br><u>J. D. Heroffer</u><br><u>G.D. GEORGESON</u>  |                  |                                   |                     |                     |                |            |
| All samples analysed gave a negative result, i.e., there were no<br>measurable amounts of asbestos.<br>This information was related by Mr. G. Dennis and he advised that<br>complete written report would be forthcoming as early as possible.<br>M.D. Horyport<br>G.D. GEORGESON   |                  |                                   | Roof studio 22      | A                   | sbestos (Am    | osite) -   |
| All samples analysed gave a negative result, i.e., there were no<br>measurable amounts of asbestos.<br>This information was related by Mr. G. Dennis and he advised that<br>complete written report would be forthcoming as early as possible.<br>M.D. Horyport<br>G.D. GEORGESON   |                  | -27                               |                     |                     |                |            |
| All samples analysed gave a negative result, i.e., there were no<br>measurable amounts of asbestos.<br>This information was related by Mr. G. Dennis and he advised that<br>complete written report would be forthcoming as early as possible.<br>M.D. Horyport<br>G.D. GEORGESON   |                  |                                   |                     |                     |                |            |
| measurable amounts of asbestos.<br>This information was related by Mr. G. Dennis and he advised that<br>complete written report would be forthcoming as early as possible.<br><i>B.D. HoryBa</i><br><u>G.D. GEORGESON</u><br>3  |                  | Air Sampl                         | ing Result          |                     |                |            |
| measurable amounts of asbestos.<br>This information was related by Mr. G. Dennis and he advised that<br>complete written report would be forthcoming as early as possible.<br><i>B.D. HoryBa</i><br><u>G.D. GEORGESON</u><br>3  |                  | All samp                          | les analysed dave a | negative result.    | i.e., ther     | e were no  |
| complete written report would be forthcoming as early as possible.<br>D. D. Georgeson<br><u>G.D. GEORGESON</u>  |                  | measurab                          | le amounts of asbes | tos.                | , ,            |            |
| complete written report would be forthcoming as early as possible.<br>D. D. Georgeson<br><u>G.D. GEORGESON</u>  |                  | This info                         |                     | d has Mar C. Daniel | e and he as    | Land Alexa |
| G.D. GEORGESON  |                  |                                   |                     |                     |                |            |
|   |                  | . comprese                        |                     | ra ba for encountry | us curiy c     |            |
|   |                  |                                   |                     |                     | $I \cap A$     |            |
|   | ж.               |                                   |                     |                     | M.D.y          | longhan    |
|   |                  |                                   | <i>8</i> ;          | ĸ                   | // //          | 0          |
|   |                  |                                   |                     |                     | $\int G.D. GE$ | ORGESON    |
|   |                  |                                   |                     |                     |                |            |
|   |                  |                                   |                     |                     |                | 14         |
|   | 970              |                                   |                     | 20                  |                |            |
|   |                  |                                   | 2                   |                     |                |            |
|   |                  |                                   |                     |                     | 12             |            |
|   |                  |                                   |                     |                     |                |            |
|   | 20               |                                   |                     |                     |                | × *        |
|   |                  | A                                 | *:                  |                     |                |            |
|   |                  |                                   |                     |                     | •              | *          |
|   |                  |                                   |                     |                     |                |            |
|   |                  |                                   |                     | ( <u>a</u> )        |                |            |
|   |                  | 1                                 |                     | 34 (A)              |                |            |
|   |                  | Ì                                 |                     |                     | .8             |            |
|   |                  | 1                                 |                     | <u>1</u>            |                |            |
|   | ÷                | 1995                              |                     | 2                   |                |            |
|   |                  |                                   |                     |                     |                |            |
|   |                  |                                   |                     |                     |                |            |
|   |                  |                                   |                     | 10 C                |                |            |
|   | 5                |                                   | 2 °                 | 9.°                 |                | in .       |

## Commonwealth Institute of Health in the University of Sydney

ABC FOI 2016-038 -Document 4 COPIED: 7.3.85 A/CAS~ HdBuildS L. Kelly (2) IndRels


Department of Occupational and Environmental Health

Telephone: (02) 660 9222 Telex: C.I.O. H.S.U. AA71942 REF:

Building A27, University of Sydney, NSW Australia 2006

880 L.

.12



10th September, 1984.

The General Manager, ABC Television Studios, 2 Pacific Highway, GORE HILL. N.S.W. 2065.

Attention: Mr G. D. Georgeson, Federal Fire Prevention and Safety Officer.

Dear Sir,

#### Presence of Asbestos Materials Gore Hill Studios

Officers of the Commonwealth Institute of Health visited the Gore Hill TV Studios, numbers 21, 22 and 23, at your request, in the company of: Mr K. Conolly, ABC Industrial Relations Officer; Mr A. Duncan, an officer of the ABC Staff Association, N.S.W. Branch; Mr G. D. Georgeson, ABC Federal Fire Prevention and Safety Officer.


The purpose of the visit was to inspect locations in the TV studios and in the connecting corridors where asbestos containing insulation was suspected to be present; to sample and assess the condition of these insulations; to determine if any health risk was posed to the occupants of the studios and, finally, to make professional recommendations for future preventive actions.

This report addresses a number of issues as follows:

- 1. The extent and condition of the asbestos material
- 2. The level of potential health risks associated with the asbestos based material
- 3. Our recommendations
- 4. Asbestos Management Programme.

### 1. Extent and Condition of the Asbestos Material

Studio 21



Not to scale. 1, 2 and 3 indicate areas on the ceiling where bulk samples were taken

The ceiling of Studio 21 is lined with fibre glass panels covered with a yellow textile fabric. Behind the panel, there is a layer of sprayed amosite (brown asbestos) in a cementitious binder [see Plates 1 and 2]. The distance between the suspended fibre glass batts and the sprayed amosite is approximately 10 cm. The asbestos insulation is well tamped on and it is, generally, in a good condition. In some areas, where maintenance work has been carried out and where the suspended ceiling has been attached, small areas of asbestos have become detached.

In the Control Room that connects to Studio 21 there is a false metal ceiling with fibre glass insulation on the back of the metal tiles. As the tiles could not be moved, it is not known whether there is any asbestos behind the tiles.

Studio 22

Ceiling insulation, eastern aspect. This insulation is similar to Studio 21. The asbestos, however, is not quite as firmly tamped as in Studio 21. Where cables have been ducted and metal straps fastened to the ceiling, the asbestos has been damaged.

In the north-eastern corner the asbestos is tamped to a dimpled appearance.

The northern and western aspects of the ceiling insulation are similar to the north-eastern corner, i.e. the asbestos is dimpled.

#### Studio 23

The false acoustic ceiling was so firmly fastened that tiles could not be removed. A sample of the insulation, taken through a gap, has been identified as <u>fibre glass</u>, using optical microscopy, polarised light/first order red and dispersion staining techniques. We were unable to ascertain what is contained behind this layer.

#### Passage-way behind Studio 23

The removal of the ceiling tiles revealed soundly encapsulated insulating material, later identified by optical microscopy using polarised light/first order red and dispersion staining techniques as amosite (brown asbestos). The encapsulating white paint is in excellent condition.

For the protection of maintenance workers the Asbestos Warning Sign should be displayed between the tiles and the encapsulated asbestos.

### 2. <u>The Level of Potential Health Risks associated with the Asbestos</u> Based Materials

Due to concern by staff of the possibility of showering dust during placements of lights, it was decided that monitoring for airborne asbestos should be carried out in Studio 22, on three occasions, representing, ideally:

## maximum activity normal activity zero activity

Monitorings were carried out on 25th, 27th July and 10th August 1984 for approximately four hours, according to the NH & MRC 'Membrane filter method for estimating airborne asbestos dust', using acceptable modifications to the graticule and counting criteria.

Results are shown in Tables 1, 2 and 3.

TABLE 1.

Result of Sampling for Airborne Asbestos Fibres in Studio 22, Gore Hill, 25th July, 1984. "Normal Activity"

Location

Control Room

southern wall

western wall

Fibres per millilitre of air

less than 0.01

less than 0.01

less than 0.01

One metre from mid section of northern wall

One metre from mid section of

One metre from mid section of

On the "cat-walk", two metres from air conditioning outlet

less than 0.01

less than 0.01

Actual conditions during sampling: Air conditioning was operating; fire door was open; activity best described as minimal to normal

3.

### <u>TABLE 2.</u> Results of Sampling for Airborne Asbestos Fibres in Studio 22, Gore Hill, 27th July, 1984. "Maximum Activity"

| Location   | Fibres per millilitre of air |
|--|------------------------------|
| Control Room   | less than 0.01               |
| One metre from mid section of southern wall                | less than 0.01               |
| One metre from mid section of western wall                 | less than 0.01               |
| One metre from mid section of northern wall                | less than 0.01               |
| One metre from mid section of eastern wall                 | less than 0.01               |
| On the "cat-walk", two metres from air conditioning outlet | less than 0.01               |

<u>Actual conditions during sampling</u>: Air conditioning was operating; fire door was open; activity was maximum during the first hour then normal for the remainder of sampling time

<u>TABLE 3.</u> Results of Sampling for Airborne Asbestos Fibres in Studio 22, Gore Hill, 10th August, 1984. "Zero Activity

#### Location

Control Room

One metre from mid section of southern wall

One metre from mid section of western wall

One metre from mid section of northern wall

One metre from mid section of eastern wall

On the "cat-walk", two metres from air conditioning outlet

less than 0.01

Fibres per millilitre of air

less than 0.01

Actual conditions during sampling: Air conditioning was not operating; fire door was open; T.V. acting training was conducted in the first hour, with lights on then all activity ceased, lights were switched off and there was no activity thereafter

Microscopic examination of the dust collected indicated the presence of the usual grit and mineral matter. Counting all fibrous material (usually paper fibres and not necessarily asbestos) indicated that the air in these locations contained values much less than 0.01 fibres per millilitre of air which is the practical detection limit

4.

of this method. The current occupational health standard for amosite asbestos is 0.1 fibres per millilitre averaged over an 8-hour day, 40-year working life.

Based on the results of this monitoring and this Department's experience in observing and measuring asbestos exposures in similar situations, we can conclude that the exposure to asbestos fibres of the occupants of this building under normal working conditions would be extremely low, if not zero, and therefore there would be no measurably increased health risk to the occupants of this building due to the presence of the asbestos materials.

International organisations involved in formulating public health policies have published comments on the health risks to building occupants from the presence of asbestos.

- The Canadian Royal Commission concludes "that the presence of friable asbestos in buildings does <u>not present</u> a health hazard to building occupants except in special circumstances where work disturbs friable asbestos-containing insulation"<sup>1</sup> (our emphasis)
- 2. The British Advisory Committee on Asbestos concludes "Our evidence of the non-occupational risk is <u>not such</u> as to prompt us to recommend the general removal of asbestos from existing buildings"<sup>2</sup> (our emphasis)
- 3. The overseas experience has been reviewed by Major and Rogers (Health Implications of Buildings incorporating Sprayed Asbestos, Clean Air, August 1984, 76-78) and conclusions presented for Australian buildings.
- 4. The National Consultative Committee on Occupational Health and Safety comments ... "Such asbestos if controlled does not represent an unacceptable risk ... Much of the asbestos found in structures today is not in need of immediate removal".

#### Conclusions

It can be concluded from the three sets of results of Sampling for Airborne Asbestos Fibres that since the sprayed-on asbestos is in a good condition and further protection is provided by the thick layer of fibre glass batts, no detectable amount of asbestos reaches the air of

../6

<sup>1</sup>Dupré, J Stefan (Chairman): Report of the Royal Commission on Matters of Health and Safety Arising from the Use of Asbestos in Ontario. Ontario Ministry of the Attorney General, 1984, page 593.

Simpson, W. (Chäirman): Advisory Committee on Asbestos, Final Report Vol. 1. London: Her Majesty's Stationery Office, 1979, page 91. the work place in Studio 22. Some of the insulation batts are deteriorating and release man-made mineral fibre (mmmf) when disturbed. This will not constitute a health hazard but may lead to technical failures in some more sensitive equipment.

The studio is, therefore, safe for continued occupation.

#### 3. Recommendations for Remedial Action

Bssed on our monitoring results, the overseas experience and on the excellent condition of the asbestos material, we <u>do not recommed</u> that the asbestos based material be immediately removed from these areas because of the possibility of contamination of the building during removal.

From our experience in supervising and monitoring asbestos removal work, we warn against unplanned wholesale removal of all asbestos materials from buildings. Our experience has been that such removal results in incressed exposure of the removal work force and increased exposures to the present and future occupants.

We recommend the implementation of an Asbestos Management and Custodial Programme that would ensure that any person involved in procedures that are likely to create asbestos dust carry out the work in a manner that will minimise his exposure and hence eliminate the potential risk to the worker and minimise any contamination of the work site.

#### 4. Asbestos Management Programme

An effective asbestos management programme requires that any work, which is likely to disturb the asbestos material, is carried out in a manner which results in minimal exposure of the worker and minimal contamination of the area. Such a programme should include the following points.

- 1. An Asbestos Register should be set up by a specially nominated officer of the Australian Broadcasting Corporation. In this Register, all locations where asbestos or asbestos-containing insulation has been found to be present, should be listed together with the condition of the asbestos and the date of inspection. Thereafter, the inspection of the asbestos in all the listed locations should become part of the annual maintenance programme. Results of these inspections must be noted in the Register.
- 2. A general clause should be inserted into all contracts let for this building. This clause should state that there is asbestos material in the building and that every time a contractor comes across this material, it must be treated in the manner outlined in the Asbestos Management Programme.

- 3. Warning signs should be placed on or near all asbestos material advising persons intending to do any work in the vicinity not to break the surface of the material. If the material is to be disturbed, then the sign should advise workmen to report to a designated safety officer conversant with the Asbestos Management Programme.
- When asbestos materials are repaired or replaced, only non-asbestos products should be used.
- 5. All asbestos waste should be stored in a separate container with a securely fitting lid and disposed of in the manner approved by the local waste authority.
- 6. All workmen involved in any work that is likely to disturb asbestos, e.g. installation of new lights, must be outfitted with the proper protective equipment. This equipment includes approved respirators (a minimum of a 3M 8710 disposable respirator) and disposable overalls. Only asbestos approved vacuum cleaners must be used [Appendix A].
- 7. When workmen remove fibre glass batts to carry out simple maintenance they should carry out the following procedures:
  - a) workmen carrying out this work should be equipped with suitable respiratory protection (a minimum of a 3M 8710 disposable respirator) and disposable overalls
  - b) all personnel and furniture should be removed from the immediate vicinity of the work area for the duration of the work
  - c) plastic sheeting (0.2 mm thick polyethylene) should be placed on the floor to catch any asbestos material that may fall from the tiles; on completion of work this plastic must be vacuumed with an asbestos approved vacuum cleaner, then carefully folded and placed into asbestos approved plastic bags
  - batts should be taken down carefully so as not to disturb any dust
  - e) any large pieces of asbestos on the batt can be placed by hand into a pre-wetted asbestos approved plastic bag (0.2 mm thick polyethylene)
  - f) each batt must be thoroughly vacuumed with an asbestos approved vacuum cleaner [Appendix A]
  - g) all asbestos waste, used disposable respirators and overalls must be placed into asbestos approved plastic bags; these bags should then be disposed of in the manner approved by the local waste authority.

7.

8. When extensive renovations are planned for any area that will involve <u>major</u> disturbance to the sprayed asbestos material, or at demolition of the building, then the asbestos material should be removed using the methods outlined in the NH & MRC code for the safe removal of asbestos based thermal/acoustic insulating materials (October 1979 - amended June 1981) by a contractor experienced in asbestos removal.

Our experience of similar removal jobs in many cities around Australia has shown that <u>thorough planning</u> and <u>strict</u> <u>supervision</u> prior to, during and after the job by experienced personnel is necessary to ensure that the procedures outlined in this code are followed by the contractor and that the building is not contaminated. This Institute will be available to advise on the preparation of contracts.

- 9. When workmen conduct repair work or maintenance on the asbestos or fibre glass batts, they should carry out the following procedures:
  - a) workmen conducting this work should wear suitable respiratory protection (a minimum of a 3M 8710 disposable respirator) and disposable overalls
  - b) they should work in a manner that does not involve breaking the surface of the asbestos
  - c) if any asbestos material is disturbed, then it should be immediately cleaned up with an asbestos approved vacuum cleaner
  - all disposable respirators and overalls should be disposed of as asbestos waste.

When renovations or maintenance work is planned for the area above the fibre glass batts, e.g. installation of new lights and this will involve disturbance of the asbestos material in small areas only, then consideration should be given to using alternate routes for these services. If alternate routes cannot be found then the area involved in the work should be stripped of asbestos material using methods available from this Institute.

We hope that you will find this report useful. Should you, or any of your contractors, have any questions about our recommended procedures related to asbestos, please do not hesitate to phone us on 660 9240.

A. Rogers, Lecturer in Occupational Hygiene.

| Yours sincerely, RECEIVED | Summer of |
|---------------------------|-----------|
| IOUIS BINCELELY,          |           |
| 2 7 FEB 1985              |           |
| Vianol                    |           |
| SELLEN FIRE/SAFETY        |           |
| G. /Denes,                | ્ય        |
| Scientific Officer.       | 2<br>5355 |

Attachments:

List of Asbestos Approved Vacuum Cleaners N.S.W. Government Asbestos Regulations Plates 1 and 2

Copy to: Mr Arthur Duncan, ABC Staff Association, N.S.W. Branch, 164 William Street, KINGS CROSS. N.S.W. 2011.




PLATE 1

Ceiling insulation in Studio 22, showing sprayed on asbestos, visible when the fibre glass is pushed back




PLATE 2

Close-up of a damaged area

APPENDIX A

Division of Industrial Relations, Division of Inspection Services

# VACUUM CLEANERS

# APPROVED AS PER FACTORIES, SHOPS AND INDUSTRIES ACT. ASBESTOS REGULATIONS AS AT 30 JUNE, 1981

| Brand Name  | Identification No.   | Approved No.   |
|-------------|--|--|
| Nilfisk     | GA 70<br>GA 71<br>GA 72<br>GÀ 73   | 1062<br>1063<br>1064<br>1065   |
| ۲           | GB 733   | 1066<br>1067<br>1232<br>1233<br>1234<br>1235                         |
| BVC         | EV 21S<br>EV 41A<br>EV 51A<br>TH 4A<br>TH 6A<br>T 17A<br>T 18A<br>T 331A<br>T 338A | 1068<br>1069<br>1070<br>1071<br>1072<br>1073<br>1074<br>1075<br>1348 |
| Amano       | V 3<br>V 5N<br>V 7.5<br>AWG 5  | 1076<br>1077<br>1078<br>1300   |
| Pullman     | JB 55<br>JB 75<br>JB 105<br>JB 365<br>JB 502<br>JB 503                             | 1097<br>1098<br>1099<br>1100<br>1101<br>1102                         |
| W.A.P Turbo | M 15   | 1302   |

J. N. Williams, CHIEF INSPECTOR, FACTORIES, SHOPS & INDUSTRIES

New South Wales Government

# Metropolitan Waste Disposal Authority

SPECIAL CONDITIONS APPLICABLE TO OCCUPIERS OF PREMISES ON WHICH ASBESTOS WASTE IS CREATED



| CATE                        | GORY 1;                          | Waste asbestos - based thermal/acoustic insulating material   |
|-----------------------------|----------------------------------|---|
| CATE                        | GORY 2:                          | Asbestos - containing dust waste  |
|                             | CORY 3:                          | Waste materials containing asbestos in a bonded matrix such as asbestos cement.   |
|                             |                                  |   |
| SPEC                        | TAL CONDI                        | TIONS APPLICABLE TO ASBESTOS WASTE CATEGORIES 1 & 2   |
| 1.                          | The occu<br>all othe             | pier shall ensure that the above trade wastes are stored separate from r wastes.  |
| 2.                          | The occu<br>condition            | pier shall ensure that the above trade wastes are stored in a wetted<br>n acceptable to the Authority.  |
| 3.                          | ing not                          | pier shall ensure that the above trade wastes are stored in 200 micrometre<br>ow density polythene bags of maximum size 1.2m high by 0.9m wide, contain-<br>more than 25kg total weight and sealed by tying with wire ties acceptable<br>uthority.                                      |
| 4.<br>: λ <sub>it</sub> . * | The occu<br>form are             | pier shall ensure that the above trade wastes in sheet, block, pipe, etc<br>stored in sealed 200 micrometre thick polythene sheeting.   |
|                             | The occup<br>systems<br>packaged | pier shall ensure that the above trade wastes removed by dust collection<br>are collected in impervious bags and if unable to be wetted are to be<br>in an outer sealed metal dust-proof container marked 'CAUTION - ASBESTOS'<br>rs of minimum height 40mm and complying with AS 1319. |
| 6.                          | The occup<br>trade was           | pier shall ensure that polythene bags and sheeting in which the above<br>stes are stored are marked 'CAUTION - ASBESTOS' in letters of minimum  |

7. The occupier shall ensure that polythene bags containing the above trade wastes are stored in leak-proof metal containers maintained in a clean condition both internally and externally.

18. The occupier shall ensure that the leak-proof metal containers are only used for the storage of the above trade wastes and are labelled in letters of minimum height 50mm and complying with AS 1319 as follows:

> DANGER - ASBESTOS WASTE ONLY AVOID CREATING DUST

9. The occupier shall ensure that the leak-proof metal containers mave a close fitting cover which prevents spillage or dispersal of the above trade wastes to the atmosphere.

10. The occupier shall ensure that the person transporting the above trade wastes from said premises is the holder of a current licence to transport the above trade wastes.

SPECIAL CONDITIONS APPLICABLE TO ASBESTOS WASTE CATEGORY 3


height 40mm and complying with AS 1319.

- :1., The occupier shall ensure that the above trade waste is stored separate from all other wastes.
- 2. The occupier shall ensure that the above trade waste is stored in a wetted condition acceptable to the Authority.
- 3. The occupier shall ensure that the above trade waste is covered during storage.
- 4. The occupier shall ensure that any dust generated from the above trade waste is subject to the special conditions applicable to asbestos waste categories 1 and 2.
  - N.B. Occupiers are advised that transporters of waste for fee or reward are required to be licensed by the Metropolitan Waste Disposal Authority.

Your attention is also drawn to the Acts and Regulations administered by the Department of Industrial Relations in respect of the handling of asbestos or material containing asbestos.

R&L/PC/04 August'84.

# **4.B.C. INTER - OFFICE MEMORANDUM**



ABC FOI 2016-038 cument 5

| ADDRESS                                   | LOCATION  | ТҮРЕ                        | PURPOSE | INSPECT./QUALIF.<br>COMPANY/AUTHORITY                                     | CONDITION<br>REC. ACTION | LAST P. DDIC<br>INSPECTION |
|---|---|-----------------------------|---------|---|--------------------------|----------------------------|
| ICHS FOREST STUDIOS<br>tic Drive,<br>ngah | •   |                             |         |   |                          | · ·                        |
| TUDIO COMPLEX<br>fic Highway              | Scenic Runway<br>Studio. Build                              | Chrysotile and Amosite      |         |   | ×                        | )<br>2500701               |
| HIII                                      | N,W.M & E Corridors<br>Studio Build.<br>Maz. floor No. M3 - | Amosite<br>Amosite          |         | *   |                          |                            |
| , *                                       | Plan Room<br>Lower ground floor,<br>Studio Build.           | Amosite                     | ×       | Occupational Health   |                          | 14.5.79                    |
| •   | Rooms 507,517,520 -<br>Tech. Service Corridor               | Amosite                     | e<br>2  | and Radiation Div.  |                          |                            |
|   | 23  |                             |         |   |                          |                            |
| *   | Lagging - Studio Build                                      |                             |         |   |                          |                            |
|   | Ceiling void - Studio<br>23<br>Ceiling void - Dubbing       | fibre                       |         |   |                          |                            |
|   | Theatrette<br>Dyeline copying machine                       | fibre                       | * ".    |   |                          |                            |
|   | Tower Build - 7th fl.                                       | in a plaster<br>cement base | ,       |   | · ·                      |                            |
| D STUDIOS<br>Forbes St<br>inghurst.       | Studio 207  | 0 fibres/mililit            | re      | Health Comm. of NSW<br>Div. Occupational Health<br>and Radiation Control. | good<br>n                | 8.10.80                    |

|  | <b>ja</b>   | p  | (************************************* |  |                          |            |
|--|---|--|--|--|--------------------------|------------|
| ADDRESS                                  | LOCATION  | TYPE   | PURPOSE                                | INSPECT./QUALIF.<br>COMPANY/AUTHORITY        | CONDITION<br>REC. ACTION | LAST PODIC |
| 0 STUDIOS<br>Forbes St.                  | Plant Room 208  | O Fibres mililit                                 | re                                     | Occupational Health<br>and Radiation Control | good                     | 8.10.80    |
| inghurst Cont.<br>5th level<br>6th level | 5th level   | Amosite )  |  | н  | 5                        | 30.4.79    |
|  | 6th level   | Aveidatite                                       | •                                      | a  | 5                        | 30.4.79    |
|  | Ceiling of Corridor an<br>underside of air duct<br>Plant Room,- 7th level | d )<br>Amoste )                                  | *                                      |  |                          | 14.5.79    |
|  | Technical area corrido<br>5th level                                       | j  |  |  |                          | 14.5.79    |
|  | PMG PABX Room - 6th<br>level  | Chrysolite )                                     |  | Ŕ  |                          | 14.5.79    |
|  | Plant Room - 7th Level  | Amosite  |  | Occupational Health and                      |                          |            |
|  | Acoustic Tile Ceiling<br>Level 3  | Asbestos<br><del>Crolidolite</del><br>Gocidolite |  | Radiation Control                            | affected areas           | 8.10.80    |
| i  | Pipe Insulation - Leve<br>5-9   |  |  |  |                          | 8.10.80    |
|  | Ceiling of PABC - Leve<br>6   | Crocidalité )<br>Chrysotile )<br>Asbestos        |  | ·  |                          | 8.10.80    |
| Lurd<br>ru<br>7<br>P<br>5                | Smoke relief rent outer<br>Level 13 - Lift machine<br>room - Nth end      | Amosite )<br>Asbestos )                          |  |  |                          | 20.8.80    |
|  | a/c supply duct - Level<br>7 N/S corridor                                 | Amosite )<br>Asbestos )                          |  |  |                          | 20.8.80    |
|  | Plumbing Duct - Level<br>5-9  | Amosite<br>Asbestos                              | 4                                      |  |                          | 20.8.80    |
|  | Cleander Room - Level 3   | Considelite 1                                    |  |  | ţ                        | 20.8.80    |

| ADÜRESS  | LOCATION   | ТҮРЕ                 | PURPOSE | INSPECT./QUALIF.<br>COMPANY/AUTHORITY | CONDITION<br>REC. ACTION | LAST R ODIC |
|--|--|----------------------|---------|---------------------------------------|--------------------------|-------------|
| DIA THEATRE<br>oria Ave,<br>swood                    |  | a<br>a               |         | 9                                     |                          |             |
| + Offices<br>William St.<br>s Cross                  | Studio 217 - air<br>conditioning ducts<br>Editing Booth - 3rd Fl<br>air conditioning ducts | Asbestos<br>Asbestos |         | 2003)<br>10 - M<br>10 - M             | ,                        |             |
| tta Building<br>Campbell St and<br>rve Road,<br>RMON | 4<br>4<br>4  |                      |         |                                       |                          | •           |
| otta Street,<br>7 Carlotta Street<br>RMON            |  |                      |         |                                       | ÷                        |             |
| dos Street,<br>3 Chandos Street,<br>_EONARDS         | All airconditioning<br>ducts   | * 10<br>*            | 2       |                                       |                          |             |
| Street,<br>eg Street,<br>RMON                        | Office Area, fire<br>retardent – sprayed on<br>steel beams                                 |                      |         |                                       |                          | ÷           |
| E.   |  | ×                    |         |                                       |                          | ,           |

| AQŪRESS   | LOCATION ·             | TYPE | PURPOSE | INSPECT./QUALIF.<br>COMPANY/AUTHORITY | CONDITION<br>REC. ACTION | LAST PE DIC<br>INSPEC ON |
|---|------------------------|------|---------|---------------------------------------|--------------------------|--------------------------|
| e Cameron Building<br>6 Dickson Ave,<br>RMON<br>- | Air conditioning ducts |      |         |                                       | ·                        |                          |
| 8 Dickson Ave,<br>RMON                            |                        |      |         |                                       |                          |                          |
| nic Hall<br>field Ave,<br>FIELD                   |                        |      | - 7     |                                       |                          |                          |
| neering Training<br>niting Street,<br>RMON        |                        |      |         | · · · · · · · · · · · · · · · · · · · |                          |                          |
| Shop<br>REPOINT                                   |                        |      |         |                                       |                          |                          |
| o 228<br>es Street<br>NGHURST                     | · · ·                  |      |         | Г.                                    |                          |                          |
| ac<br>Tizabeth Street<br>Y                        |                        | x    | v       | ,                                     |                          | ¥                        |
| icast House<br>53 Elizabeth St.<br>Y              | -                      |      |         | а<br>—                                |                          |                          |
|   |                        |      |         | -                                     |                          | 1                        |

|   |  |               | <u> </u> |                                       |                          | 9.200<br>19.200             |
|---|--|---------------|----------|---------------------------------------|--------------------------|-----------------------------|
| ADÜRESS   | LOCATION   | ТҮРЕ          | PURPOSE  | INSPECT./QUALIF.<br>COMPANY/AUTHORITY | CONDITION<br>REC. ACTION | LAST PER DDIC<br>INSPECTION |
| 2 McLachlan Ave,<br>CUTTERS BAY                     |  |               |          |                                       |                          |                             |
| lstanes Building<br>Stanley & Palmer St<br>INGHURST | Fire retardent compound<br>sprayed onto beam and<br>columns - no asbestos  | l Vermiculite |          |                                       |                          | 14.5.79                     |
| field Towers<br>Villiam Street,<br>SYDNEY           | an<br>S  |               |          |                                       | -                        | ā                           |
| AC BUILDING<br>38 William St.,<br>SYDNEY            | Airconditioning ducts<br>not ventilating or<br>exhaust systems.  | × '           |          | ,<br>,<br>1                           |                          |                             |
| TTI BUILDING<br>Hilliam St.,<br>SYDNEY              | Airconditioning ducts<br>not ventilating or<br>exhaust systems   |               |          |                                       |                          |                             |
| gton Centre<br>iverpool Street,<br>Y                | n na sana ang sana an<br>Iku |               |          |                                       |                          |                             |
| House<br>ent Street,<br>Y                           |  | a             |          |                                       |                          |                             |
| 5   |  |               |          |                                       |                          |                             |
| 8   |  |               |          |                                       |                          |                             |





Occupational Health Division (02) 660 9222 Telephone: CIOHSU AA71942

C/- School of Public Health and Tropical Medicine, Bldg A27 THE UNIVERSITY OF SYDNEY NSW 2006

Our ref.:

Telex:

9th August, 1985

ABC FOI 2016-038 **Document 6** 

Federal Fire Prevention & Safety Officer, Australian Broadcasting Commission, 145-153 Elizabeth St, SYDNEY, 2000.

Attention: Mr Grant Georgeson

Dear Sir,

# Re Compressed Board in Video Tape Area 1st floor Gore Hill Studios

This letter is to report on the bulk analysis of the compressed board sampled from the above area and received on the 30th July 1985, and the air monitoring carried out in the above area on the 29th July 1985.

optical light by sample was analysed The bulk staining dispersion red and order using lst microscopy techniques. The sample was found to contain a minor concentration of chrysotile (white asbestos).

Air monitoring was done using the NH & MRC Membrane Filter Method with acceptable modifications to the graticule and counting criteria. All results were less than 0.01 fibres/ml air. The practical detection limit of the method is 0.01 fibres/ml of air.

While carrying out the air monitoring Mr. Gary Brennan that it was a management decision to have air us informed conducted, even though there was no longer any monitoring asbestos containing material in the room, or any evidence of a source of dust which could lead to detectable airborne fibre readings.

Officers from this division have previously carried out air monitoring for the ABC under conditions where at least there is some asbestos material present. Even though this divisions experience in monitoring under similar situations indicated that airborne fibre levels would be immeasurably low. Air monitoring has been carried out only due to staff demands and the potential

> St Martins Tower, 31 Market St., SYDNEY, N.S.W. 2000 G.P.O. Box 58, SYDNEY, N.S.W. 2001 Telephone: 2902377 Facsimile: 296340

for industrial action. Under such circumstances air monitoring has been used to quantify (within the limits of the method) the amount of airborne asbestos fibre and to allay the fears and educate the staff in asbestos matters. However, it is our opinion that to air monitor where no asbestos is present is totally irrational !

We suggest that the present asbestos "witch hunts", resulting from unfounded staff and management demands, achieves the following.

1) It helps fuel peoples unfounded fears about asbestos in buildings.

2) It sets precedents which lead to massive future expenditure on asbestos removal and associated activities.

3) It wastes hygienists time, thereby distracting their activities from areas where real occupational hazards exist.

If any further information on this matter is required an officer from this division would be pleased to be of service.

Alan Rogers Lecturer Occupational Health Yours faithfully,

T. Johnson

Terry Johnsen Scientific Officer



National Occupational Health and Safety Commission

ABC FOI 2016-038

| Telephone:(02) 660 9222Tropical Medicine, Bldg A27Telex:177243THE UNIVERSITY OF SYDNEYNSW 2006 |    |
|--|----|
| THE UNIVERSITY OF SYDNEY NSW 2000  |    |
|  |    |
| Dur ref.:<br>C.C. lignes Kalley.<br>FIRE ATT   |    |
| CINE - A Marine Providence   |    |
| Australian Broadcasting Corporation<br>Head Office<br>Box 9994 GPO<br>Sydney NSW 2001          |    |
| Sydney NSW 2001  |    |
| attention: Mr G. D. Georgeson RECEIVED   |    |
| Federal Fire Prevention & <u>31 DEC 1985</u><br>Safety Officer                                 |    |
| Federal Fire Prevention & 31 DEC 1985<br>Safety Officer  | 44 |
|  |    |
| Asbestos Sample - Gore Hill Studios  |    |

A sample of millboard taken from the cupboard located in Control Room, Studio 24, ground floor of the above premises was received by this Division on 4th December, 1985.

The sample was analysed by optical light microscopy using first order red and dispersion staining techniques. The results are as follows:

Chrysotile (white) Asbestos - major (greater than 15%)


If any further information is required on this matter an officer from this Division would be pleased to be of service.

Yours faithfully

Ichnoe

Terry Johnsen Scientific Officer

18 December 1985



St Martins Tower, 31 Market St., SYDNEY, N.S.W. 2000 G.P.O. Box 58, SYDNEY, N.S.W. 2001



National Occupational Health and Safety Commission

Occupational Health Division

Telephone: (02) 660 9222 Telex: 177243 C/- School of Public Health and Tropical Medicine, Bldg A27 THE UNIVERSITY OF SYDNEY NSW 2006

ABC FOI 2016-038 Document 8

Our ref.:

Australian Broadcasting Corporation Broadcast House 145-153 Elizabeth Street Sydney 2000

attention Mr G. D. Georgeson Federal Fire Protection & Safety Officer

Dear Sir

Fibro Sheet Sample Gore Hill, Staging Workshops (opposite Peter Balsam Pavilion)

The sample attached to your letter of 12th December 1985 has been analysed for asbestos content using optical microscopy, polarised light/{irst order red and dispersion staining techniques.

Results are shown in Table 1.

Table 1 Results of analysis for asbestos

Location

Fibre determination

Staging Workshop

Both Chrysotile, White Asbestos, and Amosite, Grey Asbestos, present.

Yours sincerely

910

George Denes Scientifie Officer 31 December 1985



St Martins Tower, 31 Market St., SYDNEY, N.S.W. 2000 G.P.O. Box 58, SYDNEY, N.S.W. 2001

2-47-106

AMDEL - N.S.W. Division, Unit 2, 32A Sirius Road, LANE COVE NSW 2066

Telephone: (02) 428 5033

March 4, 1986.

RECEIVED

13 MAR 1986

FIRE/SAFELY

Mr. Grant Georgenson Australian Broadcasting Commission P.O. Box 9994 SYDNEY NSW 2001

Our Ref: 1156

Dear Mr Georgenson,

We enclose herewith our report on the asbestos monitoring tests which we carried out for your organisation.

If you have any queries on the report please do not hesitate to contact us.

We thank you for giving AMDEL the opportunity to carry out the work and look forward to being of further assistance to you.

Yours sincerely,

W.A. Wyatt, Manager - Consultant Services,

for J. Newton Manager, NSW Division.

J. M.


Head Office: Flemington Street, Frewville South Australia 5063 Telephone (08) 79 1662 Telex: Amdel AA82520 Pilot Plant: Osman Place Thebarton, S.A. Telephone (08) 43 5733 Telex: Amdel AA82725 Branch Laboratories: Melbourne, Vic. Telephone (03) 645 3093 Perth, W.A. Telephone (09) 325 7311 Telex: Amdel AA94893 Sydney, N.S.W. Telephone (02) 439 7735 Telex: Amdel AA20053 Townsville Queensland 4814



The Australian neral Development Laboratories

igton Street, Frewville, South Australia 5063 Adelaide (08) 79 1662 Telex AA82520

Please address all correspondence to '.O. Box 114 Eastwood SA 5063 In reply quote:





 $\langle \rangle$  .

March 4, 1986

Australian Broadcasting Commission P.O. Box 9994 SYDNEY NSW 2001

REPORT NO: 1156/CC04

Your Reference: Verbal

Work Required: Airborne Asbestos Monitoring

Location: ABC Workshop - Gore Hill

Investigation by: John Flint

Reported by: W.A. Wyatt, AMDEL NSW.

Summary 💦

Following a request by the client, monitoring was carried out by AMDEL to determine the presence and level of airborne asbestos dust at the dates and locations shown in the appended data.

The method used to determine the concentrations of asbestos fibre is the "Membrane filter method for estimating airborne asbestos dust" published by the N.H & M.R.C.



# APPENDIX 1

February 19, 1986

# AIRBORNE ASBESTOS MONITORING RESULTS

|          |             |                                      | Page 1   |                          |                                  |                                     |
|----------|-------------|--------------------------------------|--|--------------------------|----------------------------------|-------------------------------------|
| Number   | <u>Date</u> | Sampl                                | <u>e</u> <u>Location</u>   |                          | <u>Time</u><br>(mins)            | <u>Concentration</u><br>(Fibres/ml) |
| Customer | Ref. No:    | <u>1156</u>                          | × .,   |                          |                                  |                                     |
| 1565     | 5712785     | ABC 1<br>ABC 2<br>ABC 3<br>ABC 4     | STUDIO NEAR PLAST<br>OUTSIDE STUDIO 22<br>WORKSHUP SOUTH **<br>WORKSHOP NORTH<br>** NOT TO NHMRC | 340<br>345<br>340<br>330 | <0.01<br><0.01<br><0.01<br><0.01 |                                     |
| 1580     | 6/12/85     | ABC 5<br>ABC 6<br>ABC 7<br>ABC 8     | WORKSHOP NORTH<br>WORKSHOP SOUTH<br>STUDIO NEAR PLASTIC<br>OUTSIDE MENS TOILET                   | 435<br>435<br>420<br>425 | <0.01<br><0.01<br><0.01<br><0.01 | u.                                  |
| 1622     | 10/12/85    | ABC 9<br>ABC 10<br>ABC 11<br>ABC 12  | UUTSIDE MENS TOILETS<br>PROF AREA<br>NORTH SIDE PLASTIC WORK<br>SOUTH SIDE PLASTIC WORK          | 425<br>410<br>380<br>375 | <0.01<br><0.01<br><0.01<br><0.01 | 1<br>1.                             |
| 1636     | 11/12/85    | ABC 13<br>ABC 14<br>ABC 15<br>ABC 16 | WORKSHOF SOUTH<br>WORKSHOP NORTH<br>PROP AREA<br>OUTSIDE MENS TOILETS                            | 395<br>395<br>395<br>395 | <0.01<br><0.01<br><0.01<br><0.01 | 9                                   |
| 1643     | 12/12/85    | ABC 17<br>ABC 18                     | LEFT<br>RIGHT<br>CLEARANCE OF ABOVE  | 240<br>240               | <0.01<br><0.01                   |                                     |



National Occupational Health and Safety Commission

> C/- School of Public Health and Tropical Medicine, Bldg A27 THE UNIVERSITY OF SYDNEY NSW 2006

> > 11th June 1986

ABC FOI 2016-038 Document 10

Australian Broadcasting Corporation Broadcast House 145-153 Elizabeth Street SYDNEY 2000

Attention: Mr. Grant Georgeson Federal Fire & Safety Officer

Dear Sir,

Air monitoring for Asbestos was carried out by an officer of this Division, at your request, on the first floor offices of the Peter Balmson Pavillion, adjacent to the corrugated fibro roof of the Prop-store, on 27th May 1986.

As background information to your request, it was explained that Staff was concerned about the fibro roof releasing Asbestos to the air and on the occasions when the windows are open next to the roof, Asbestos may drift into the Office, which then may present an extra health risk to the occupant.

To measure the Asbestos that the roof may release and then can find its way to the office area, three windows were opened and monitoring pumps were placed on the three window ledges.

The air sampling was carried out using the NH&MRC approved "Membrane Filter Method for Estimating Airborne Asbestos Dust", with acceptable modifications to the graticule and to counting criteria. Analytical results are listed in Table 1.

TABLE 1. Results of analyses for Asbestos in Peter Balmson Pavillion 27.5.86.

LOCATION

FIBRES PER ML OF AIR

Admin. Office Window. right end (facing the roof)

Less than 0.01

Less than 0.01

Admin Office Window, mid position (facing the roof)

Prop. Store Window left (facing the roof)

Less than 0.01



30th Floor, St Martins Tower 31 Market Street, SYDNEY NSW 2000 GPO Box 58, SYDNEY NSW 2001 Telephone 265 7555 Tolex 177243, Eaccimile 265 7538

#### HEALTH RISK ASSESSMENT

The limit of detection for the Membrane Filter method is 0.01 fibre per millilitre of air. The Hygiene limit for Chrysotile, White Asbestos, which has been identified in the cement matrix of the roof, is 1 fibre per millilitre of air, as a time weighted average for 8 hours a day, five days a week and for a working life of 50 years.

It can be concluded from the above data as well as from numerous overseas and local publications that no measurable extra Health Risk that can be attributed to the Asbestos content of the roof, exists to the occupants of these offices.

It should be remembered, however, that the fibro roof should not be subjected to mechanical disturbance (e.g., grinding, drilling etc.) and in all instances, the NSW Government Regulations concerning the removal and disposal of fibro sheets must be followed.

Should you require any further information on any aspects of this report, please do not hesitate to contact us on (02) 265 7344.

Yours sincerely

GEORGE DENES

Scientific Officer