

[illegible]

LOCATION	TYPE	PURPOSE / USE	Inspector-qualified Company Authority	Condition Recommended Action	LAST PERIODIC INSPECTION
iling.	Amosite asbestos in cementitious matrix		Dept of Housing & Construction		20/7/84
ster dusts	Chrysotile in cementitious matrix			no danger	20/7/84

ADDRESS	LOCATION	TYPE	PURPOSE / USE	Inspector Qualification Company/Authority	Condition Recommended Action	LAST PERIODIC INSPECTION
47-73 MAIN NORTH EAST ROAD COBLENWOOD SA						
- TV Studio Complex						
Studio 51 - Plant Room	Chilled water Pipes	Sample being analysed			Poor	7/2/80
Studio 51 - Plant Room	Electric heaters in ducts sprinkler systems expansion joints	Mill Board Asbestos		Dept of Housing	Good	7/2/80
Studio 51 - Booths 1 & 2, Announcers Booth and studio sup.	Electric heaters in ducts air handling plants	Asbestos Rope		e Construction	Good	7/2/80
Studio 53 - Control Room	Electric heaters in ducts	Mill board Asbestos			Good	7/2/80
Studio 51	ceiling	Amosite (grey)			Good	7/2/80
News and Film Complex						
Plant room	Electric heaters in ducts	Mill board Asbestos		Dept of Housing e Construction	Good	7/2/80
Graphics Plant Room	Electric heaters in ducts	Mill board Asbestos			Good	
O.B. and Canteen Block						
O.B. Maintenance area	Electric heaters in duct	Mill board Asbestos		Dept of Housing e Construction	Good	7/2/80
O.B. Maintenance area	Canteen waste pipes	Sample being analysed			Good	7/2/80
Administrative Bldg.						
basement to roof	Emergency diesel alternator exhaust Partly metal clag in basement	Mill board and blanket Asbestos		Dept of Housing e Construction	Good	7/2/80
roof tank room	Fire equipment diesel	Asbestos rope		Dept of Housing e Construction	Good	7/2/80
B/E to 9th floor, East and West	Electric risers (floor penetrations)	Crocidolite (blue)			Good	
Studio wing	Electric risers (floor penetrations)	Crocidolite		Dept of Housing e Construction	Good	7/2/80
Ground floor to eighth floor	Hydraulic risers (floor penetration)	Crocidolite plus another type being analysed			Good	7/2/80
Main switchboard basement	wall penetration	Crocidolite		The Australian Mineralogy	Poor	7/2/80
Tank Room Basement 9th	wall penetration	Crocidolite			Poor	

ADDRESS	LOCATION	TYPE	PURPOSE/USE	INSPECTOR QUALIFICATIONS COMPANY - AUTHORITY	CONDITION - RECOMMENDED ACTION	LAST PERIODIC INSPECTION
37-39-40-41 ROSETTA STREET COLLINSWOOD SA						
Administration Bldg						
9th floor	A/C Switchboards (fan)	crocidolite			Poor	7/2/80
Studio wing	Hydraulic raiser	crocidolite		Dept of	Poor	7/2/80
A/C Plant room	2nd floor & ceiling	chrysotile (white)		Housing & Construction	Good	7/2/80
Television Building						23/3/79
Studio 51	ceiling	Limpet asbestos	insulation	Def		23/3/79
Plant Room No. 2 Radio Ring	ceiling	Limpet asbestos	insulation			23/3/79
All floors of Adm. Bldg	Electrical Service ducts	Limpet asbestos				23/3/79
TV A/C plant	chilled water lines	Asbestos lagging				23/3/79
Collinswood Complex:						
Admin & Radio Complex	Electrical Raisers various floor & wall penetrations	crocidolite (blue)				27/11/84
	Fire Equipment Diesel	Asbestos Rope				27/11/84
	Flue, Roof Tank room					
Television complex - TV Studio 51	Sprayed ceiling	Amosite (Grey)		State Dept of Labour & Industry		
Admin. & Radio Complex:	Air Handling, Plant Room ceiling, 2nd floor Radio wing	chrysotile (white)			Good	27/11/84
Admin & Radio Complex	Diesel Power Generation Flues, Basement to roof level in Western and A/C Raiser	Asbestos, millboard slabs asbestos blankets			Good	
Admin & Radio Complex	Pipe Penetration 1st to 9th floor in Hydraulic Raiser	Asbestos millboard slabs asbestos blankets				

[illegible]

ADDRESS	LOCATION	TYPE	PURPOSE/USE	Inspector Qualification Company/Authority	Condition Recommended Action	LAST PERIODIC INSPECTION
SOUTHERN CROSS ARCADE				Dept of		
52-62 KING WILLIAM STREET SA				Administrative		
				Services		

ADDRESS	LOCATION	TYPE	PURPOSE / USE	CONDITION	LAST PERIODIC INSPECTION
ROSE HILL STUDIOS 191 ADELAIDE TERRACE PERTH WA					
GOLDEN WEST NETWORK BLDG 72 WITTENDON STREET ST BUNBURY WA					
17 BURVILLE STREET ALBANY WA					
84 AINSWORTH STREET GERALDTON WA					

ADDRESS	LOCATION	TYPE	PURPOSE / USE	Inspector - Qualifications Company / Authority	Condition Recommended Action	LAST PERIODIC INSPECTION
40 WARD STREET KALGOORLIE WA						
27 ROBINSON STREET PORT HEDLAND WA	In Residence		Used as staff Residence	ADHAC Inspectors WA Public Health Department	not a health hazard	7.9.84
ABC SHOP CARILLON CENTRE MAY STREET PERTH WA						
216 YORK STREET ALBANY						

ADDRESS	LOCATION	TYPE
SPENCER + STIRLING STREETS BUNBURY WA		
193 MARINE TERRACE GERALDTON WA		
PORTER + BROOKMAN STREET KALGOORLIE WA		
RICHARDSON STREET PORT HEDLAND WA		
TV Studio 61	ceiling	asbestos

[illegible]

ADDRESS	LOCATION	TYPE	PURPOSE / USE	Inspector Qualification Company / Authority	Condition Recommended Action	LAST PERIODIC INSPECTION
BROADCAST HOUSE						
22-26 ELIZABETH STREET HOBART TAS		asbestos material		TAS. Dept of	All Asbestos	9/8/84
TV Building - Plant rooms,	(a/c systems, ducts)	(Heat resistant		labour and	removed under	
Boiler House,		textiles, Thermal		Industry	regulations	
workshops		insulation products				
Studio 71	ceiling	floor tiles (vinyl asbestos)				
171 MACQUARIE STREET HOBART TAS						
16-32 MONTELEONE RETREAT HOBART TAS						
33-35 CATHER STREET BURNIE TAS						

ADDRESS	LOCATION	TYPE
5 JOHANSEN STREET ALICE SPRINGS NT		
11 JOHANSEN STREET ALICE SPRINGS NT		
SPENCER STREET ALICE SPRINGS NT		
18 BENNETT STREET DARWIN NT	Insulating Wool wrapped around generator & auto- within high voltage cables	
7 BLAKE STREET DARWIN NT		
9 GORDON STREET PARAP DARWIN		

[illegible]

ADDRESS	LOCATION	TYPE	PURPOSE / USE	Inspector - Qualification Company / Authority	Condition Recommended Action	LAST PERIODIC INSPECTION
22 URBANT STREET PARAP DARWIN NT						
2 KNOWLES STREET JINGILI DARWIN NT						
23 ROTHDALE ROAD JINGILI DARWIN NT						
3 SAWYER STREET JINGILI						
10 WICKHAM & BREMER ST. FANNIE BAY DARWIN						
6 BEATRICE STREET STUART PARK DARWIN						

ADDRESS	LOCATION	TYPE	PURPOSE / USE	Inspector - Qualification Company / Authority	Condition Recommended Action	LAST PERIODIC INSPECTION
7 BEATRICE STREET STUART PARK DARWIN NT						
8 BEATRICE STREET STUART PARK DARWIN NT						
10 BEATRICE STREET STUART PARK DARWIN NT						
4 GODFREY COURT, LARRAKIYAH DARWIN						
YANGWUA DRIVE AMULA DARWIN NT						
13 BITTERN STREET WULAGI DARWIN						

ADDRESS	LOCATION	TYPE	PURPOSE / USE	Inspector Company / Authority	Condition Recommended Action	LAST PERIODIC INSPECTION
31 ROSELLA CRESC. WULAGI DARWIN NT						

