

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

ADDRESS	LOCATION	TYPE	PURPOSE / USE	Inspector Qualification Company / Authority	Condition Recommended Action	LAST PERIODIC INSPECTION
HICETT WORKSHOPS						
1123 NEPEAN HIGHWAY HICETT						
Bldg - Hicett - Dept: ^{Production Facilities} Wardrobe Workshop	Floor	Vinyl Asbestos Tiles			Good	
	Roof	Corrugated AC Sheet			Brittle	
	Heater Flues	AC Pipe			Good	
" " Dept: ^{Production Facilities} Set Painters Workshop	Floor	Vinyl Asbestos Tiles				
	Roof	Corrugated AC Sheet			Brittle	
	Fire Pipes	Asbestos			Good	
" " Dept: ^{Production Facilities} Props Makers Workshop	Ceiling	AC Sheet			Good	
	Roof	Corrugated AC Sheet			Brittle	
" " Dept: ^{Production Facilities} Wardrobe Store	Ceiling	AC Sheet			Good	
	Roof	Corrugated AC Sheet			Brittle	
" " Dept: ^{Production Facilities} Props Store	Roof	Corrugated AC Sheet			Brittle	
	Pipe lagging	Asbestos			Good	
	Disused Boiler				Asbestos in boiler casing	
" " Dept: ^{Production Facilities} Set makers Workshop	Floor	Vinyl Asbestos Tiles			Good	
	ceiling	AC Sheet			Good	
" " Dept: Service Area - Toilets stairs	Floor	Vinyl Asbestos Tiles			Good	

[illegible]

