

[illegible]

ADDRESS	LOCATION	TYPE	PURPOSE / USE	Inspector Qualification Company/Authority	Condition - Recommended Action	LAST PERIODIC INSPECTION
T.V. STUDIO COMPLEX						
PACIFIC HWY, GORE HILL						
Studio Bldg	Scenic Runway	Chrysotile & Amosite				
Studio Bldg	N.W. & E corridors	Amosite		Occupational Health and Radiation Centre		14/5/79
Plant Room	MAZ floor NO. M3	Amosite				
Studio Bldg	Lower G/F	Amosite				
Technical Service Corridor	Rooms 507, 517, 520	Amosite		Occupational Health and Radiation Centre		
studio 21, 22 and 23	ceiling	Amosite		" " " "		
Studio Bldg -	Lower G/F. Pipe lagging	Amosite				
Studio 23	ceiling void	Man made mineral Fibre		Occupational Health and Radiation Centre		14/5/79
Dubbing Theatre	ceiling void	Man made mineral Fibre				14/5/79
Tower Building - 7 th floor	Dye line copying machine	amosite, asbestos in a plaster cement base.				
Proficiency Stone	-			Division of Occupational Health and Radiation Centre.		

ADDRESS	LOCATION	TYPE	PURPOSE / USE	Inspector - Qualification Company/Authority	Condition Recommended Action	LAST PERIODIC INSPECTION
RADIO STUDIOS						
184 FORRECE ST, DARLINGHURST						
Section: Studio 207		O fibres millilitre			good	8 Oct. 1980
Phone Room 208		" " "			good	8 Oct. 1980
5 TH Level		Amosite		Health Commission of NSW Division of Occupational Health and Radiation Control	Remove or seal affected areas.	30/4/79
6 TH Level		Chrysotile				30/4/79
Plant Room - 7 TH Level	ceiling of corridor and underside of air duct	Amosite				14/5/79
Technical Area Corridors - 5 TH Level		Amosite				14/5/79
PM G PABX Room - 6 TH Level		Chrysotile				14/5/79
Plant Room 7 TH Level		Amosite asbestos				
Level 3	acoustic tile ceiling	Crocidolite				8/10/80
Level 5-9	pipe insulation	Amosite				8/10/80
Level 6	ceiling of PABX	Chrysotile asbestos				2/10/80
Level 13 - lift machine room N. and	Smoke relief vent outer	amosite asbestos				20/8/80
Level 7 - N/S corridor	A/C supply duct	amosite asbestos				20/8/80
Level 5-9 Plumbing duct		amosite asbestos				20/8/80
Level 3 - cleaner room		crocidolite asbestos				20/8/80

[illegible]

[illegible]

ADDRESS	LOCATION	TYPE	PURPOSE / USE	Inspector - Qualification Company/Authority	Condition Recommended Action	LAST PERIODIC INSPECTION
3589555						
2 JJJ + OFFICES						
171 WILLIAM ST, KINGS CROSS						
Studio 217: 2JJ Systems	Air conditioning ducts	asbestos				
Editing booth 3rd floor	Air conditioning ducts	asbestos				

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]